

Figure 3B-6.
Crowley Lake Outlet Conductivity, 1940-1991





Figure 3B-7.
Conductivity of LADWP Well Water in the Owens River Basin



Note: See text for well field names.