




Thin, firm salt crust, upper end of salt deposits



Thin, buckled, fragile salt crust, middle portion of salt deposits

Note: Photographs were taken below Ten Mile Road on April 24, 1992.

Figure 3H-21.
Crusted Salt Deposits