


Thick, powdery deposit, lower portion of salt deposits



Thick, powdery deposit, same area as preceding photograph

Note: Photographs were taken below Ten Mile Road on April 24, 1992.

Figure 3H-22.
Powdery Salt Deposits